

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402648953

Date Received:  
04/05/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Gomez, Jason</u>		<u>jason.gomez@state.co.us</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>ediefitzgerald@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103290  
Inspection Date: 09/17/2020 FIR Submit Date: 09/17/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 309197

Location Name: APACHE CANYON-633S67W Number: 35SESW County: LAS ANIMAS  
Qtrqr: SESW Sec: 35 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.123390 Longitude: -104.858660

FACILITY - API Number: 05-071-00 Facility ID: 289993

Facility Name: APACHE CANYON Number: 35-14-2  
Qtrqr: SESW Sec: 35 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.123390 Longitude: -104.858660

CORRECTIVE ACTIONS:

1  CA# 142120

Corrective Action: MAINTAIN WEEDS, COMPLY WITH RULE 603.f. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 11/05/2020

THE WEEDS WERE MECHANICALLY REMOVED FROM THE LOCATION. SEE PHOTO LOG FOR DETAILS.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2  CA# 142121

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 03/31/2021

Operator  
Comment:

THE ACCESS ROAD WAS CROWNED TO CREATE SHEET FLOW AND ELIMINATE THE SURFACE EROSION THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE BAR DITCH AND THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER RUN OFF FROM THE ACCESS ROAD. THE SEDIMENT ACCUMULATION IN THE CULVERT INLETS WERE REMOVED TO ALLOW STORMWATER TO FLOW THROUGH CULVERTS. THE EROSION IN THE BAR DITCH WAS BACK FILLED AND COMPACTED WITH THE TIRE ON THE BLADE.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: Sr. Environmental Tech.

Date: 4/5/2021 4:44:39 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402648953	FIR RESOLUTION SUBMITTED
402648957	PHOTO LOG

Total Attach: 2 Files