

Inspection Photos

4/16/2021

Operator: TEP ROCKY MOUNTAIN LLC #
96850

Location ID: 324218
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 324218



Photo 1: Photo taken from the west end of the Location, facing northeast. Photos 1-3 provide an overview of the Location from northeast, east to south



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 324218



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the south end of the Location, facing south. Photo shows erosion degradation on interim areas due to stormwater runoff from the Location and access road; stormwater and erosion control measures on the Location missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 324218



Photo 5: Photo taken from the interim areas on the south end of the Location, facing northwest. Photo shows erosion degradation on interim areas due to stormwater runoff from the Location and access road; stormwater and erosion control measures on the Location missing or insufficient. Additional reclamation required.



Photo 6: Photo taken from the interim areas on the south end of the Location. Photo shows erosion degradation and sediment deposition from stormwater runoff.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 324218



Photo 7: Photo taken from the interim areas on the south end of the Location, facing northwest. Photo shows erosion degradation and sediment deposition from stormwater runoff. Additional reclamation required.



Photo 8: Photo taken from the interim areas on the south end of the Location, facing north. Photo shows erosion degradation and sediment deposition from stormwater runoff. Additional reclamation required.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 324218



Photo 9: Photo taken from the interim areas on the southwest end of the Location, facing east. Photo shows erosion degradation and sediment deposition from stormwater runoff. Additional reclamation required.



Photo 10: Photo taken from the interim areas on the southwest end of the Location, facing northwest. Photo shows erosion degradation and sediment deposition from stormwater runoff. Additional reclamation required.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 324218



Photo 11: Photo taken from the ditch along the access road, on the west end of the Location, facing west. Photo shows erosion degradation at ditch, and interim areas of the Location; control measure has not been maintained in proper functioning condition. Stormwater ditch has not been constructed with an appropriate outlet; control measure has not been installed in accordance with good engineering practices. Additional reclamation required on interim areas.



Photo 12: See comments under photo 11.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 324218



Photo 13: See comments under photo 11.



Photo 14: Photo taken from east end of the Location, facing northwest. Photo shows outlet of the stormwater diversion ditch that runs along the north end of the Location. Stormwater ditch has not been constructed with an appropriate outlet; control measure has not been installed in accordance with good engineering practices.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 324218



Photo 15: 2016 Google earth aerial image. Photo shows overview of the Location. Photo shows southern interim areas where degradation due to strowmater is evident.

