

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/23/2021

Submitted Date:

04/23/2021

Document Number:

696303152**FIELD INSPECTION FORM**
 Loc ID 310112 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10691Name of Operator: PHOENIX RESOURCES LLCAddress: 5566 S SYCAMORE STREETCity: LITTLETON State: CO Zip: 80120**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Eisenach, Jason		jeisenach@phxresources.com	
Heffner, Taylor	303-219-3362	theffner@phxresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296168	WELL	TA	05/01/2019	OW	123-25920	STATE 2	TA

General Comment:
[Follow-UP Inspection to FIR 696300687 dated 10.10.2019.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Wellhead. See photos		
Corrective Action:	Comply with Rule 606	Date:	05/10/2021
Type	OTHER		
Comment:	Stained Soil at Gas Engine, see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	05/10/2021
Type	DEBRIS		
Comment:	Old Deadman Markers on ground. See photos		
Corrective Action:	Comply with Rule 606	Date:	05/10/2021
Type	WEEDS		
Comment:	Clear out dead Weeds and prevent future growth at the Treater and Tank Battery Areas. See photos		
Corrective Action:	Comply with Rule 606	Date:	05/10/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	SEPARATOR		

Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	TA Wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:	Shares berm with the Crude Oil Tank									
Corrective Action:								Date:		
Contents		#	Capacity	Type		Tank ID	SE GPS			

PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.655900,-104.208150
Comment:					
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			

Flaring:

Type			
Comment:			
Corrective Action:			

Inspected FacilitiesFacility ID: 296168 Type: WELL API Number: 123-25920 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA - MIT 08.22.2018

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 04/22/2021 at approximately 10:59, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Phoenix Resources LLC, State #2, Location #310112 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Unmarked Risers at Wellhead. See photos. Comply with Rule 606. Corrective Action Date 05.10.2021</p> <p>Clear out dead weeds and prevent future growth at Treater and Tank Battery areas. See photos. Comply with Rule 606. Corrective Action Date 05.10.2021</p> <p>Old Deadman Markers on ground. See photos. Comply with Rule 606. Corrective Action Date 05.10.2021</p> <p>Stained Soil at Gas Engine. See photos. Comply with Rule 905.e. Corrective Action Date 05.10.2021</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	04/23/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303153	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411894