

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21SENW

Location ID: 334750



Photo #3600 from entrance to location.



Photo #3601 Location lacks stabilization

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21SENW

Location ID: 334750



Photo #3603 location lacks stabilization



Photo #3604 No form of tracking BMP at entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21SENW

Location ID: 334750



Photo #3602 No tank battery sign located at the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources