

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2021

Submitted Date:

04/15/2021

Document Number:

701002781

FIELD INSPECTION FORMLoc ID 321573 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 61250

Name of Operator: MULL DRILLING COMPANY INC

Address: 1700 N WATERFRONT PKWY B#1200

City: WICHITA State: KS Zip: 67206-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Morgan, John		john.morgan@state.co.us	
Brown, Ray	719-343-5186	rbrown@mulldrilling.com	
Quint, Craig		craig.quint@state.co.us	
Akers, Tracy	719-342-1813	takers@mulldrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207332	WELL	IJ	05/09/2016	ERIW	017-06267	MULL UNIT (MCCORMICK 3) 16	AC

General Comment:

5 Year UIC MIT

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Metal panels around solar panel and dehydrator		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead and chemical tank		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 3		
Comment:	Solar powered cathodic rectifier, electric panel and chemical tank (laying on the ground)		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Gas dryer (TPACK) w/gas scrubber. East of wellhead		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 207332 Type: WELL API Number: 017-06267 Status: IJ Insp. Status: AC**Underground Injection Control**UIC Violation: Failed MIT Maximum Injection Pressure: _____UIC Routine

Inj./Tube:	Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg)	Previous Test Pressure _____	MPP _____
TC:	Pressure or inches of Hg _____	Previous Test Pressure _____	Inj Zone: <u>MRRW</u>
Brhd:	Pressure or inches of Hg _____	Previous Test Pressure _____	Last MIT: <u>04/22/2016</u>
			AnnMTReq: <u>NO</u>

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: PUMP FEEDTest Type: 5 Year Tbg psi: 540 Csg psi: 0 PSIG BH psi: _____Insp. Status: Fail Leak Type: Casing

Comment: INITIAL CSG HAD LIGHT BLOW, DIED IMMEDIATELY. MIRU EXTREME HEAT. LOADED W/2BBL. PRESSURED CSG TO 600 PSIG. 5 MIN 400#. 10 MIN 100#. 15 MIN 100#. -500 PSI LOSS

Corrective Action: Immediately shut in well and disconnect flowline or disable/LOTO injection pump. Contact COGCC Engineering Dept within 10 days for further directives

Date: 04/25/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402661779	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5405981
701002809	Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5405980