

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Photo 1 – Spill area. Fencing up around open excavation.



Photo 2 – Open excavation. Impacts remain in situ. Trash observed in excavation.

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



**Photo 3 – Open excavation. Impacts remain in situ.
Trash observed in excavation.**



**Photo 4 – Open excavation. Impacts remain in situ.
Trash observed in excavation.**

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Photo 5 –Trash observed in excavation.



Photo 6 – Additional disturbed area on site. Trash observed in disturbed area.

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Photo 7 – Trash on location; additional area of disturbed soils.



Photo 8 – Oily soils stockpiled on location. Lining not present under the entirety of soils pile.

Inspection Photos
Camenisch 1 sx Flowline Release
Spill ID 479713 (AC)



Photo 9 – Stained soil observed around open excavation.



Photo 10 – Stained soil observed around open excavation.