

Inspection Photos

API: 043-06059

Operator: JAVERNICK OIL

Inspection Date: 4/22/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06059 | Date: 4/22/2021

Inspection Photos



Photo 1. Facing southwest toward the former access road. This area is not stabilized with vegetation and there is erosion occurring.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06059 | Date: 4/22/2021

Inspection Photos



Photo 2. Facing back to the northeast toward the road. There has been straw bales placed along this area however, straw bales are not a long term erosion control and have filled in with sediment. There is an erosion channel directed down toward the main road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06059 | Date: 4/22/2021

Inspection Photos



Photo 3. There is an erosion gully along the road that is approximately 2-3 ft. deep. This area needs to be filled in and stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06059 | Date: 4/22/2021

Inspection Photos



Photo 4. Facing toward the bottom of the erosion shown in previous photo. There is straw bales that appear to have washed out of gully. The gully needs to be filled in and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06059 | Date: 4/22/2021

Inspection Photos



Photo 5. Facing back northeast along the former access road. It appears that the stormwater from the location is directed down the road which is causing erosion issues shown in previous photos.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06059 | Date: 4/22/2021