

# Inspection Photos

API: 043-06196

Operator: JAVERNICK OIL

Inspection Date: 10/19/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 1.** Facing south along the main access road. There is erosion along this area of the road which needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 2.** Facing northeast along the access road. The access road has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 3.** Facing northeast along the access road. The access road has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 4.** Facing southwest at the location. The cut slope is shown in the right side of the photo. The location has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020

## Inspection Photos



**Photo 5.** There is an open hole which is about 4.5 ft. deep. There is cement debris next to the hole which appears to be from plugging of the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06196 | Date: 10/19/2020