

Inspection Photos

API: 043-40014

Operator: JAVERNICK OIL

Inspection Date: 2/9/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40014 | Date: 2/9/2021

Inspection Photos



Photo 1. Facing northeast along the access road. The road has not been recontoured and reclaimed. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40014 | Date: 2/9/2021

Inspection Photos



Photo 2. Facing northeast along the access road. The road has not been recontoured and reclaimed. The soils are bare of vegetation and susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40014 | Date: 2/9/2021

Inspection Photos



Photo 3. There is an access road that leads northeast to the Drapper4 well site which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40014 | Date: 2/9/2021

Inspection Photos



Photo 4. Facing southwest along the access road between the Hassler 24 and Drapper4 well site. This area has not been recontoured and reclaimed and is susceptible to further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40014 | Date: 2/9/2021