

Inspection Photos
Location Name: Cosslet A 9 Flowline
Spill ID 478542



COGCC Environmental Inspection
40.07533, -104.96683, 4943.6ft, 314°
04/19/2021 11:31:49 AM

**Photo 1 – Free product observed on groundwater.
Flowlines exposed and trash in excavation.**



COGCC Environmental Inspection
40.07545, -104.96687, 4948.1ft, 97°
04/19/2021 11:34:18 AM

**Photo 2 – Free product observed on groundwater.
Flowlines exposed and trash in excavation.**

Inspection Photos
Location Name: Cosslet A 9 Flowline
Spill ID 478542



**Photo 3 – Free product observed on groundwater.
Flowlines exposed.**



**Photo 4 – New fencing constructed, remnants of old
fence left as trash.**

Inspection Photos
Location Name: Cosslet A 9 Flowline
Spill ID 478542



**Photo 5 – Stockpiled soils with inadequate BMP's;
wetland in background.**



**Photo 6 – Stockpiled soils with inadequate BMP's;
wetland in background.**