

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment:

PHOTO 3: APPEARS TO BE AN OIL SOAKED RAG NEXT TO PRIVE MOVER INSIDE SOUND WALLS.

Corrective Action:

PICK UP ALL TRASH ON AND AROUND LOCATION, COMPLY WITH RULE 606. CA DATE 5-14-21.

Date: 05/14/2021

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Gas Meter Run

1

Comment:

CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

1

Comment:

PHOTO 4: Bradenhead inaccessible or not visible.

Corrective Action:

Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)

Date: 05/10/2021

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 293958 Type: WELL API Number: 071-09459 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [PHOTO 5: ANTIFREEZE IN PRIME MOVER SKID WITH NO WILDLIFE PROTECTION.](#)

Corrective Action: **COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.**

Date: 04/27/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104299	insp. photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413400