

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #3611 from entrance to location.




Photo #3612 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #2975 from inspection #699802654 conducted on 2/24/21.



Photo #3616 location lacks stabilization.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #2976 from inspection #699802654 conducted on 2/24/21.



Photo #3614 No form of tracking BMP located at entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-67S95W /21NWNW

Location ID: 335047



Photo #2976 from inspection #699802654 conducted on 2/24/21.