

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402672674

Date Received:

04/27/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Dylan Thomsen</u>		<u>timothy.thomsen@state.co.us</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergyllc.com</u>
<u>Atwater, Bonnie</u>	<u>432-755-0212</u>	<u>batwater@ogrisop.com</u>
<u>Fitzgerald, Edie</u>		<u>ediefitzgerald@tcenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690200707

Inspection Date: 10/01/2020

FIR Submit Date: 10/06/2020

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308578

Location Name: APACHE CANYON-634S68W Number: 2SESW County: LAS ANIMAS

Qtrqr: SESW Sec: 2 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.107470 Longitude: -104.965890

FACILITY - API Number: 05-071- -00 Facility ID: 274909

Facility Name: APACHE CANYON Number: 2-14

Qtrqr: SESW Sec: 2 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.107470 Longitude: -104.965890

CORRECTIVE ACTIONS:

1 ☒ CA# 142598

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: _____

Response: CA COMPLETED

Date of Completion: 04/20/2021

THE MAIN LEASE ROAD SURFACE WAS CROWNED TO REMOVE THE SURFACE EROSION AND

Operator Comment: ESTABLISH SHEET FLOW. THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER ON THE NORTH SIDE OF THE ROAD TO DIRECT RUN OFF TO AN ARMORED CALL OUT, WHICH DRAINS INTO AN EXISTING SEDIMENT BASIN. WATER TURNOUTS WERE INSTALLED TO REMOVE WATER FROM THE BAR DITCH REDUCING THE VOLUME AND THE VELOCITY OF THE RUN OFF. THE SEDIMENT ACCUMULATION WAS REMOVED FROM THE CULVERT INLET. SEE ATTACHED PHOTO LOG FOR DETAILS.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 4/27/2021 3:36:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402672674	FIR RESOLUTION SUBMITTED
402672701	PHOTO LOG

Total Attach: 2 Files