

Inspection Photos

4/27/2021

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 398846

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 1: Photo taken from the west end of the Location, facing northeast. Photos 1-3 provide an overview of the Location from northeast, southeast to south.



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the west end of the Location, facing west. Photo shows access west access road leading to the Location has not been reclaimed .

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 5: Photo taken from the access road west of the Location, facing east. Photo shows access west access road leading to the Location has not been reclaimed .



Photo 6: Photo taken from the northeast end of the Location, facing north. Photo shows access road leading to the Location has not been reclaimed.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 7: Photo taken from the Location. Photo shows example of pipe debris remaining on the Location.



Photo 8: Photo taken from the Location. Photo shows example of pipe debris remaining on the Location.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 9: Photo taken from the east end of the Location. Photo shows example of cable debris remaining on the Location.



Photo 10: Previous inspections observed that stormwater erosion control BMPs were missing, or insufficient on the Location, and that cracking/rilling in soils were observed.

Photo shows control measures remain missing or insufficient to stabilize/protect the Location; erosion degradation remains evident.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 398846



Photo 11: Previous inspections observed that stormwater erosion control BMPs were missing, or insufficient on the Location, and that cracking/rilling in soils were observed.

Photo shows control measures remain missing or insufficient to stabilize/protect the Location; erosion degradation remains evident.



Photo 12: Previous inspections observed that stormwater erosion control BMPs were missing, or insufficient on the Location, and that cracking/rilling in soils were observed.

Photo shows control measures remain missing or insufficient to stabilize/protect the Location; erosion degradation remains evident.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 13: Photo taken from the east end of the Location, facing south. Photo shows control measures remain missing or insufficient to manage runoff from the Location.



Photo 14: Photo taken from the east end of the Location, facing north. Photo shows control measures remain missing or insufficient to manage runoff from the Location.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 15: Photo taken from the southwest corner of the Location, facing north. Photo shows perimeter stormwater ditch. Ditch BMP has not been constructed in accordance with good engineering practices; BMP ends on the southwest end of the location and does not have a sufficient outlet to allow for sediment laden-free stormwater discharge.



Photo 16: Photo taken from the southwest corner of the Location, facing east. See comments under photo 15.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 17: Photo taken from the Location. Inspector was unable to observe desirable vegetative establishment; Location is progressing towards a Halogeton monoculture. This is a Colorado State Listed noxious weed and requires management.



Photo 18: Continued from photo 17. Vegetative germination observed in photo is Halogeton.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 398846



Photo 19: 1955 USGS aerial imagery. Well was spud 1957. Photo shows Location of the Lubauer 33A well prior to O&G disturbance. Photo shows access roads did not pre-exist Location.