

Inspection Photos

API: 071-09287

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/27/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09287 | Date: 4/27/2021

Inspection Photos



Photo 1. Facing northwest the beginning of the access road. The road has not been recontoured and reclaimed. There are signs of stormwater erosion down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 4/27/2021

Inspection Photos



Photo 2. Facing south along the access road. The road has not been recontoured and reclaimed. There are signs of stormwater erosion down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 4/27/2021

Inspection Photos



Photo 3. The electric utility remains along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 4/27/2021

Inspection Photos



Photo 4. Facing west toward the location. The location has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 4/27/2021

Inspection Photos



Photo 5. Facing west at the location. The soils are not stabilized and are susceptible to erosion. BMP's have not been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 4/27/2021

Inspection Photos



Photo 6. Facing northeast at the location. The location is not stabilized and there are signs of erosion. BMP's have not been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09287 | Date: 4/27/2021

Inspection Photos



Photo 7. The electric utility remains at the southwest side of the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 071-09287 | Date: 4/27/2021