

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 1 – Spill area. Fencing down around open excavation. Trash on location.



Photo 2 – Spill area. Fencing down around open excavation. Soils stockpiled on location. Trash on location.

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 3 – Open excavation. Free product observed on groundwater. Impacts remain in situ.



Photo 4 – Open excavation. Free product observed on groundwater. Impacts remain in situ.

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 5 – Impacted soils remain on surface outside of excavation area.



Photo 6 – Impacted soils remain on surface outside of excavation area. Soils stockpiled on location with inadequate BMPs.

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 7 – Soils stored on location with inadequate BMPs



Photo 8 – Soils stored on location with inadequate BMPs

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 9 – Soils stored on location with inadequate BMPs



Photo 10 – Soils stored on location with inadequate BMPs