

**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 1 – Spill area. Fencing up around open excavation.**



**Photo 2 – Spill excavation. Impacts remain in situ. Trash observed in open excavation.**



**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 3 – Spill excavation. Impacts remain in situ.  
Trash observed in open excavation.**



**Photo 4 – Spill excavation. Impacts remain in situ.  
Trash observed in open excavation.**



**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 5 – Oily soils stockpiled on location. Lining does not adequately protect surface soils.**



**Photo 6 – Oily soils stockpiled on location. Lining does not adequately protect surface soils.**



**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 7 – Stained soil observed around open excavation.**



**Photo 8 – Stained soil observed around open excavation.**



**Inspection Photos**  
**Camenisch 1 sx Flowline Release**  
**Spill ID 479713 (AC)**



**Photo 9 – Additional disturbed area on site. Trash observed in disturbed area.**



**Photo 10 – Trash on location.**