

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SESW

Location ID: 324218



Photo #3662 from entrance to location.



Photo #3665 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SESW

Location ID: 324218



**Photo #3666 Rill erosion.**



**Photo #3667 Rill erosion.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /34SESW

Location ID: 324218



**Photo #3668 No velocity checks.**



**Photo #3669 Sediment is being transported off of location.**