

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/19/2021

Submitted Date:

04/23/2021

Document Number:

689501186

FIELD INSPECTION FORM

Loc ID 479000 Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		mknop@kpk.com	
, KPK		cogcc@kpk.com	All Inspections
Axelson, John		john.axelson@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478005	SPILL OR RELEASE	CL			-	H. Huett Consolidation Release	EI

General Comment:

This is an environmental inspection of Remediation Project No. 16135/Spill ID 478005(CL). Any corrective actions from previous inspections that have not been addressed are still applicable.

[Photos attached to document site conditions.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	No fencing is present around open excavation		
Corrective Action:	Secure access to excavation in compliance with Rule 913.b.(5).B.i and COGCC Guidance 913.b.(5)B i-v.	Date:	04/26/2021

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 478005 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Excavation was in process at the time of inspection. Excavation has been open since initial inspection conducted 9/16/2020. Form 27 Doc #402653879 (4/9/2021) notes "The excavation was backfilled before samples were taken to confirm clean up at the landowners request to allow cattle in the pasture."

Corrective Action: Per previous CA's Operator shall provide sample location diagram, summary table of analytical results compared to table 915-1 standards, analytical lab reports, any disposal manifests and gate tickets not previously provided, and documentation on the source/location and volume of the clean fill dirt imported on site via Supplemental Form 27 no later than 45 days from the Spill Report Date (10/29/2020). Within 7 days Operaor shall submit a Supplemental Form 27 with corrected and accurate narrative regarding site history (4/26/2021).

Date: 10/29/2020

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
	oakmank	04/21/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402669771	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411981
689501187	Field Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411967