

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/22/2021

Submitted Date:

04/22/2021

Document Number:

699802967

**FIELD INSPECTION FORM**

Loc ID 335031	Inspector Name: De Paolo, Corey	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 30 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerusoilandgas.com	
, BLM		jbyers@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286629	WELL	PR	09/04/2008	GW	045-12715	FEDERAL 19-10 (PI19)	PR
294688	WELL	PR	02/26/2008	GW	045-15570	FEDERAL 19-9 (PI-19)	PR
294689	WELL	PR	09/21/2008	GW	045-15571	FEDERAL 19-9BB (PI-19)	PR
294690	WELL	PR	09/20/2008	GW	045-15572	FEDERAL 19-10BB (PI19)	PR
294691	WELL	PR	09/04/2008	GW	045-15573	FEDERAL 20-12BB (PI-19)	PR
294692	WELL	PR	09/21/2008	GW	045-15574	FEDERAL 19-15BB(PI-19)	PR
295827	WELL	PR	09/20/2008	GW	045-15815	FEDERAL 20-5 (PI19)	PR
295828	WELL	PR	09/23/2008	GW	045-15814	FEDERAL 20-13BB (PI19)	PR
295829	WELL	PR	09/25/2008	GW	045-15813	FEDERAL 19-16 (PI-19)	PR

**General Comment:**

COGCC Inspection Report Summary

On Thursday 4/22/21 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at CAERUS PICEANCE LLC FEDERAL-67S95W /19NESE, Location #335031 in Garfield County Colorado.

Refer to document #699802547 inspection conducted on 2/4/21. All previous corrective actions have been completed. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a corrective action date of 7/22/21.
- 2) Location lacks stabilization. No form of tracking BMP at entrance to location with a corrective action date of 5/7/21.

- Location is located on in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign missing required information		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.	Date:	07/22/2021
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Bradenhead	# 9		

Comment:	Pressure transducers located on all braden heads. All braden head valves are accessible.			Date:	
Corrective Action:				Date:	
Type: Emission Control Device	# 1				
Comment:	Connected to Braden head of Federal 19-9 well.			Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 9				
Comment:	All meter runs have been calibrated in the last year.			Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 9				
Comment:	All wells on plunger lift			Date:	
Corrective Action:				Date:	
Type: Pig Station	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	Summit midstream			Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	5	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					

**Paint**

Condition	Adequate	
Other (Content)		

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	Field Flare	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	286629	Type:	WELL	API Number:	045-12715	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294688	Type:	WELL	API Number:	045-15570	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294689	Type:	WELL	API Number:	045-15571	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294690	Type:	WELL	API Number:	045-15572	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294691	Type:	WELL	API Number:	045-15573	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	294692	Type:	WELL	API Number:	045-15574	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	295827	Type:	WELL	API Number:	045-15815	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	295828	Type:	WELL	API Number:	045-15814	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID:	295829	Type:	WELL	API Number:	045-15813	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		Chemical tank
Other	Fail					No form of tracking BMP
Berms						
		Culverts				
		Sediment Traps				
		Ditches				
		Gravel				
Sediment Traps						
Gravel						Gavel by wellheads
		Compaction				
		Berms				
Ditches						
Compaction	Fail					Location lacks stabilization
		Check Dams				
				Material Handling And Spill Prevention		Methanol tank

Comment: Location lacks stabilization. No form of tracking BMP at entrance to location.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 05/07/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<u>Refer to Signs/Markers and Storm water for corrective actions.</u>	depaoloc	04/22/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402669726	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411943">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411943</a>
699802968	Photos for Insp. #699802967	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411937">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5411937</a>