

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2021

Submitted Date:

04/30/2021

Document Number:

700702661

FIELD INSPECTION FORM
 Loc ID 335522 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295978	WELL	PR	08/01/2020	GW	045-15864	JOLLEY 16-17D	PR
298691	WELL	PR	09/01/2015	GW	045-17338	JOLLEY 16-23D	PR
298693	WELL	PR	04/18/2009	GW	045-17340	HILTON 16-36D	PR
298696	WELL	PR	01/01/2021	GW	045-17343	HILTON KP 632-16	PR
298701	WELL	PR	03/19/2009	GW	045-17344	JOLLEY 16-16D	PR
298705	WELL	PR	01/01/2021	GW	045-17346	JOLLEY KP 511-16	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 4/29/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP KP 22-16, at Location # 335522 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.

During this inspection the following compliance issues were observed:

1. Unmarked dead man
2. Staining at tanks and stained material in a trash can behind separators
3. Unused equipment (chemical tank)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Staining at tanks and stained material in a trash can behind separators		
Corrective Action:	remove all stained material	Date:	05/31/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (chemical tank) at separators		
Corrective Action:	remove unused equipment	Date:	05/31/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 2		corrective date
Comment:	One chemical tank at well heads and one chemical tank at separators (unused) both in plastic containments		
Corrective Action:		Date:	

Type: Horizontal Heater Treater	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:	Braden heads have telemetry for monitoring. One braden head is tied to sales		
Corrective Action:			Date:
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLs	HEATED STEEL AST		,	
Comment:	Two tanks are NOT heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: Ramsey, Scott

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID:	295978	Type:	WELL	API Number: 045-15864 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:		Date:		
Facility ID:	298691	Type:	WELL	API Number: 045-17338 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:		Date:		
Facility ID:	298693	Type:	WELL	API Number: 045-17340 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:		Date:		
Facility ID:	298696	Type:	WELL	API Number: 045-17343 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:		Date:		
Facility ID:	298701	Type:	WELL	API Number: 045-17344 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:		Date:		
Facility ID:	298705	Type:	WELL	API Number: 045-17346 Status: PR Insp. Status: PR
Producing Well				
Comment:	producing			
Corrective Action:		Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
Ditches						
		Check Dams				
Berms						
		Rip Rap				

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad, there is no evidence of a tracking pad at time of inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	301539	1433937	
	374696	1433944	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702668	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5418448