

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/23/2021

Submitted Date:

04/26/2021

Document Number:

701500466

FIELD INSPECTION FORMLoc ID 316038 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|--------------|----------------------------------|---------|
| Freeman, Kris | 254-717-0435 | kfreeman@31operating.com | |
| Thompson, Bud | | BLThomps@BLM.gov | |
| Rosenberg, Kelly | | kelly.rosenberg@state.co.us | |
| Ikenouye, Teri | | teri.ikenouye@state.co.us | |
| COGCC, Engineering | 303-894-2100 | dnr_cogccEngineering@state.co.us | |
| Boulger, Levin | | lboulger@31operating.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 231967 | WELL | SI | 10/01/2020 | GW | 103-09638 | FEDERAL 29-9 | SI |

General Comment:

A routine inspection identified the following compliance issues:

- 1) Debris on location.
- 2) Bradenhead access not present.
- 3) Production history not current.

This is a summary of inspection report 701500466.

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|-----|-------------|
| Comment: | 911 | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|---------------------|-------|------------|
| Type | DEBRIS | | |
| Comment: | Debris on location. | | |
| Corrective Action: | Remove debris. | Date: | 05/12/2021 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|---------------------------|--|-------|-----------------|
| Type: Deadman # & Marked | # 4 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Telemetry. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead access not present. | | |
| Corrective Action: | Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). | Date: | 05/26/2021 |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chemical container. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 231967 Type: WELL API Number: 103-09638 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last reported monthly operations were January 2021 and none recorded July 2020 to September 2020. Most recent reported production June 2020. Report past due monthly operations.

Submit required Form 7(s) to COGCC per rule 413.a.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gradient Terraces | | | | | | |

Comment: No significant soil migration, erosion or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402670613 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5412661 |
| 701500467 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5412653 |