

TEP
KP 23-17
Location # 335208



Location entrance signage is illegible

TEP
KP 23-17
Location # 335208



Lack of stabilization/compaction

TEP
KP 23-17
Location # 335208



location



location

TEP
KP 23-17
Location # 335208



Location/lack of tank battery signage



location

TEP
KP 23-17
Location # 335208



Lack of stabilization/compaction

TEP
KP 23-17
Location # 335208



Lack of stabilization/compaction

TEP
KP 23-17
Location # 335208



Cut slope on south side of location shows signs of erosion and lack of stabilization.



TEP
KP 23-17
Location # 335208



Cut slope on south side of location shows signs of erosion and lack of stabilization.

