

**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 1 – Spill area. Fencing has been repaired around open excavation. Trash on location.**



**Photo 2 – Trash on location.**



**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 3 – Open excavation. Free product observed on groundwater. Impacts remain in situ.**



**Photo 4 – Open excavation. Free product observed on groundwater. Impacts remain in situ.**



**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 5 – Impacted soils remain on surface outside of excavation area.**



**Photo 6 – Impacted soils remain on surface outside of excavation area. Soils stockpiled on location with inadequate BMPs.**



**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 7 – Soils stored on location with inadequate BMPs**



**Photo 8 – Soils stored on location with inadequate BMPs**



**Inspection Photos**  
**Paul Heinze #1 Flowline**  
**Spill ID 479232 (AC)**



**Photo 9 – Soils stored on location with inadequate BMPs**



**Photo 10 – Trash on location**