

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2021

Submitted Date:

05/05/2021

Document Number:

693700771

**FIELD INSPECTION FORM**

Loc ID 318500 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Inspections, KPK		cogcc@kpk.com	<a href="#">All KPK Inspections</a>
Axelson, John		john.axelson@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479484	SPILL OR RELEASE	AC	02/23/2021		-	Woolley#1	EI

**General Comment:**

COGCC inspection of Spill ID 479484 on the Woolley 1 flowline, followup to Field Inspection Report #693700748. No changes since previous inspection, spill excavation remains open.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		40.100933,-104.983330
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment: <span style="color: blue;">Earthern containment berm has eroded</span>				
Corrective Action: <span style="color: red;">Repair secondary containment berm around produced water vessel</span>				Date: <u>05/28/2021</u>

**Venting:**

Yes/No	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
	Date: <input type="text"/>

**Flaring:**

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
	Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 479484 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: [COGCC Inspection of Woolley 1 flowline release. Flowline excavation has not been backfilled and material stockpile remains on location. Closure of Spill ID 479484 remains unresolved.](#)

Corrective Action: Operator to verify source of material stockpiled on location and compliance with Table 915-1. Operator to submit a Form 19 Supplemental Report with required verification of stockpile and verification that flowline excavation has been backfilled and reclaimed, supported by photodocumentation.

Date: 05/21/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700776	Woolleey #1 flowline photos 5-5-2021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421718">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421718</a>