

Inspection Photos

Operator: Beeman Oil and Gas
API: 067-09363
Date: 5/5/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area facing eastward from the northwestern corner.



Photo 3. View of the western project area from the northwestern corner facing southward. Vegetation is largely continuous with surrounding field, and comprised of scattered grasses (not identifiable at this time), field bindweed, and Russian knapweed. Unused equipment needs to be removed and properly stored offsite.



Photo 4. View of tank facilities located east of the well location.



Photo 5. View of reference area comprised of open field, comprised of scattered grasses (not identifiable at this time), field bindweed, and Russian knapweed.