

Inspection Photos
Operator: Williford Res.
API: 067-07253
Date: 5/5/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area facing southward from the northwestern corner. Vegetation is largely continuous with surrounding field. Grasses such as Indian ricegrass, and dense weeds such as Russian knapweed observed.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of reference area comprised of open field, comprised of scattered grasses (not identifiable at this time), field bindweed, and Russian knapweed.