

## Inspection Photos

Location Name: LR J15 595 PAD

Location ID: 335568

Inspection Date: May 6, 2021



Location sign.



Additional material that was not observed during a September 24, 2020 Inspection (Doc #699700196). Additional material had a detectable hydrocarbon odor and some potential staining was observed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: LR J15 595 PAD**  
**Location ID: 335568**  
**Inspection Date: May 6, 2021**



**Additional material that was not observed during a September 24, 2020 Inspection (Doc #699700196). Additional material had a detectable hydrocarbon odor and some potential staining was observed. Note the stormwater accumulations located in vehicle ruts in the landfarm material.**



**Steel pipeline leading from well API 05-045-11288 to a structure that is associated with Spill/Release Point ID 474500, Remediation #15535 remediation activities.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: LR J15 595 PAD**  
**Location ID: 335568**  
**Inspection Date: May 6, 2021**



May 6, 2021 11:47:43 AM  
39.61102474N 108.03818282W  
Altitude: 2544.9m  
Speed: 0.0km/h

**Steel pipeline leading from well API 05-045-11288 to a structure that is associated with Spill/Release Point ID 474500, Remediation #15535 remediation activities.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources