

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2021

Submitted Date:

05/11/2021

Document Number:

699700244

**FIELD INSPECTION FORM**Loc ID 335568 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 11117 RIVER RUN BLVD

City: BAKERSFIELD State: CA Zip: 93311

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hughes, Jim		jimo.hughes@state.co.us	
Armstrong, Jon		jarmstrong@bry.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280598	WELL	PR	12/11/2014	GW	045-11288	LONG RIDGE LR15D J15 595	EI
280599	WELL	PR	12/15/2011	GW	045-11287	LONG RIDGE 06A J15 595	EI
443342	LAND APPLICATION SITE	CL	09/25/2015		-	Long Ridge J15 595	EI
451608	LAND APPLICATION SITE	CL	08/02/2017		-	J 15 Land Application Old Pit 451608	EI
474500	SPILL OR RELEASE	CL			-	Long Ridge J15	EI
479912	SPILL OR RELEASE	AC			-	LR Leak 2021	EI

**General Comment:**

On May 6, 2021 COGCC Environmental Staff (John Heil) conducted an environmental field inspection of BERRY PETROLEUM COMPANY LLC (Berry operator #10091) LONG RIDGE J15 595 Location ID 335568.

The purpose of this inspection is to examine the landfarm associated with spill/Release Point ID 474500, Remediation #15535.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
Other		<= 1 bbl		
Comment:	Stormwater accumulations located in vehicle ruts in the larndfarm material.			
Corrective Action:	Standing water in the vehicle ruts is in contact with E&P waste and shall be disposed properly as E&P waste.			Date: 05/18/2021

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>280598</u>	Type:	<u>WELL</u>	API Number:	<u>045-11288</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>280599</u>	Type:	<u>WELL</u>	API Number:	<u>045-11287</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>443342</u>	Type:	<u>LAND</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>451608</u>	Type:	<u>LAND</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>474500</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>479912</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: See Spill/Release Point ID 474500, Remediation #15535 for more information. Impacted material from the spill/release excavation is currently being landfarmed on the J15 Location (Location ID 335568). The landfarm is located on the north side of the well pad and surrounds the wells on the east, west and north sides. Additional material was observed on the southeast side of the landfarm that was not observed during a September 24, 2020 Inspection (Doc #699700196). This additional material had a detectable hydrocarbon odor and some potential staining was observed. A 2-inch surface steel pipeline was observed leading from well API 05-045-11288 to a structure that is associated with Spill/Release Point ID 474500, Remediation #15535 remediation activities. See attached photos for details.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700245	20210506 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5426099">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5426099</a>