

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/11/2021

Submitted Date:

05/11/2021

Document Number:

700702711

FIELD INSPECTION FORM
 Loc ID 335541 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 950 17TH STREET, SUITE 1900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289392	WELL	PR	06/18/2011	GW	045-13754	O'Toole A1	PR
289393	WELL	PR	06/18/2011	GW	045-13753	O'Toole A2	PR
289394	WELL	PR	01/01/2021	GW	045-13752	O'TOOLE A3	PR
289395	WELL	PR	02/21/2007	GW	045-13751	O'TOOLE A4	PR
301931	WELL	PR	08/01/2012	GW	045-18327	O'Toole A6	PR
301932	WELL	PR	02/17/2012	GW	045-18328	O'Toole A7	PR
301933	WELL	PR	08/01/2012	GW	045-18329	O'Toole A5	PR
301934	WELL	PR	06/17/2011	GW	045-18330	O'Toole A8	PR
421530	WELL	PR	06/19/2011	GW	045-20400	O'Toole A9	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 5/11/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Otoole A, at Location # 335541 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection. Some C/A's from previous inspections documents # 700701954 and 700702240 have been completed. Therefore C/A dates remain the same.

Inventory on location remains the same as previous inspection.

During this inspection the following compliance issues were observed:

1. Location still shows signs of lack of stabilization/compaction on pad (C/A date 1/5/2021)
2. Unmarked dead men

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor		
Comment:	tied into tank battery		
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	289392	Type:	WELL	API Number: 045-13754	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing on plunger lift					
Corrective Action:						Date:
Facility ID:	289393	Type:	WELL	API Number: 045-13753	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing on plunger lift					
Corrective Action:						Date:
Facility ID:	289394	Type:	WELL	API Number: 045-13752	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing on plunger lift					
Corrective Action:						Date:
Facility ID:	289395	Type:	WELL	API Number: 045-13751	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing on plunger lift					
Corrective Action:						Date:
Facility ID:	301931	Type:	WELL	API Number: 045-18327	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing on plunger lift					
Corrective Action:						Date:
Facility ID:	301932	Type:	WELL	API Number: 045-18328	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing on plunger lift					
Corrective Action:						Date:
Facility ID:	301933	Type:	WELL	API Number: 045-18329	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing on plunger lift					
Corrective Action:						Date:
Facility ID:	301934	Type:	WELL	API Number: 045-18330	Status: PR	Insp. Status: PR
Producing Well						
Comment:	producing on plunger lift					
Corrective Action:						Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Also location is within or in close proximity to the 411 water protection area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of a tracking pad at time of inspection.
1. Location still shows signs of lack of stabilization/compaction on pad (C/A date 1/5/2021)

Corrective Action: **Install or repair required BMPs**

Date: 01/05/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702717	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5426284