



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Two tanks have signage that is no longer legible. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605h.	Date:	08/05/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	No 24hr operator emergency # displayed. See attached photo.	
Corrective Action:	Install sign to comply with Rule 605.e.	Date: 08/05/2021

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment, unused risers on various parts of location. See attached photos		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: [Shares containment with other tanks.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	STEEL AST		,

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Paint**

Condition Adequate \_\_\_\_\_

Other (Content) UNKNOWN \_\_\_\_\_

Other (Capacity) UNKNOWN \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: [Shares containment with other tanks.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Paint**

Condition Adequate \_\_\_\_\_

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Venting:**

Yes/No NO \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Flaring:**

Type \_\_\_\_\_

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 418006 Type: WELL API Number: 123-31810 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA  
Form 4 DOC#: 402495403 (in process)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      **Weather Conditions: raining, mud                      On Tuesday, May 4, 2021 at approximately 14:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at LAZY D ZN 03-15HZ (Longs Peak Resources), at location #: 458561 in WELD COUNTY Colorado.                      While there, I observed a shut in facility.                      During this inspection the following possible compliance issues were observed:                      1. No 24hr operator emergency # displayed on tank battery sign/wellhead sign. Install sign to comply with Rule 605.e. (Corrective Action Date: August 5, 2021) See attached photo #1.                      2. Two tanks display signs that are no longer legible. Install sign to comply with Rule 605h. (Corrective Action Date: August 5, 2021) See attached photos #2, 3.                      3. Unused equipment near tank battery and wellhead. Unused risers south of tank battery. Riser must be LO/TO within 24 HRS by operator or remove. (Corrective Active Date: August 5, 2021) See attached photos #5, 6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	05/05/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402680281	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420878">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420878</a>
679603865	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420870">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5420870</a>