

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/05/2021

Submitted Date:

05/05/2021

Document Number:

693700771

FIELD INSPECTION FORM
 Loc ID 318500 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
479484	SPILL OR RELEASE	AC	02/23/2021		-	Woolley#1	EI

General Comment:

COGCC inspection of Spill ID 479484 on the Woolley 1 flowline, followup to Field Inspection Report #693700748. No changes since previous inspection, spill excavation remains open.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		40.100933,-104.983330	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	Earthen containment berm has eroded			
Corrective Action:	Repair secondary containment berm around produced water vessel			Date: 05/28/2021

Venting:

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Environmental**Spill/Remediation:**

Comment: [COGCC Inspection of Woolley 1 flowline release. Flowline excavation has not been backfilled and material stockpile remains on location. Closure of Spill ID 479484 remains unresolved.](#)

Corrective Action: [Operator to verify source of material stockpiled on location and compliance with Table 915-1. Operator to submit a Form 19 Supplemental Report with required verification of stockpile and verification that flowline excavation has been backfilled and reclaimed, supported by photodocumentation.](#)

Date: 05/21/2021

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402681028	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421738
693700776	Woolleey #1 flowline photos 5-5-2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5421718