

# Inspection Photos

5/11/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335090

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335090



**Photo 1:** Photo taken from the west end of the production area, facing north. Photos 1-3 provide an overview of the Location from north, east to south.



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 335090



**Photo 3:** See comments under photo 1.



**Photo 4:** Photo taken from the cut slopes on the west end of the Location. Slopes have not revegetated; BMPs to provide long term protection and stabilization are missing or insufficient.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 335090



**Photo 5:** Photo taken from the cut slopes on the west end of the Location. BMPs to provide long term protection and stabilization are missing or insufficient.



**Photo 6:** Photo taken from the cut slopes on the west end of the Location. BMPs to provide long term protection and stabilization are missing or insufficient.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 335090



**Photo 7:** Photo taken from the slopes on the northwest end of the Location. Areas of stormwater rilling and degradation observed in these areas. 6 foot measuring stick for reference.



**Photo 8:** See comments under photo 7.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 335090



**Photo 9:** Photo taken from the stormwater ditch/berm on the northwest end of the Location. Photo shows areas where erosion was observed on the berm.



**Photo 10:** Photo taken from the tank battery. Photo shows control measures to stabilize the production area are missing or insufficient.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 335090



**Photo 11:** Photo taken from the southwest end of the Location, facing south. Photo shows control measures to stabilize the production area are missing or insufficient.



**Photo 12:** Photo taken from the access road, facing south. Photo shows example of erosion degradation observed on access road.

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335090



**Photo 13:** Photo taken from the access road entrances, facing southwest. Photo shows BMPs to stabilize production areas/access road and to prevent off-location sediment transport during wet conditions are missing or insufficient