Inspection Photos

5/11/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324441

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC





Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-3 provide an overview of the Location from east, south to southwest





Photo 2: See comments under photo 1.





Photo 3: See comments under photo 1.





Photo 4: Photo of wellhead





Photo 5 Photos 5-8 taken from the production area. Photos show control measures to stabilize and protect unpaved areas of the Location are missing or insufficient.





Photo 6: See comments under photo 5.





Photo 7: See comments under photo 5. Hard-hat for reference.





Photo 8: See comments under photo 5. Hard-hat for reference.





Photo 9: Photo taken from the sediment trap on the south end of the Location. Sediment trap has not been maintained in proper functioning condition.





Photo 10: Photo taken from the sediment trap on the south end of the Location. Sediment trap has not been maintained in proper functioning condition. Erosion degradation evident.





Photo 11: Photo taken from the sediment trap on the south end of the Location. Sediment trap has not been maintained in proper functioning condition. Erosion degradation evident. .





Photo 12: Photo taken from the sediment trap on the south end of the Location. Sediment trap has not been maintained in proper functioning condition. Erosion degradation evident.





Photo 13: Photo taken from the interim areas on the west end of the Location, facing north. Desirable perennial vegetative establishment is sparse; interim areas largely bare. Vegetation observed on interim areas predominantly undesirable weedy plant species.





Photo 14: Photo taken from the interim areas on the southeast end of the Location, facing northeast. See comments under photo 13.





Photo 15: Photo taken from the interim areas on the north end of the Location, facing west. See comments under photo 13.





Photo 16: Photo taken from the soil stockpile on the northwest end of the Location. Photo shows vegetation observed on stockpile are undesirable weedy plant species. Stockpile not protected in accordance with Rule 1002.c





Photo 17: Continued from photo 16. Photo shows vegetation observed on stockpile are undesirable weedy plant species. Stockpile not protected in accordance with Rule 1002.c





Photo 18: Continued from photo 16. Photo shows vegetation observed on stockpile are undesirable weedy plant species. Stockpile not protected in accordance with Rule 1002.c





Photo 19: Photo shows vegetation on the adjacent reference areas.

