

Inspection Photos
Location Name: Wray Mesa 36-34-47-20
API: 05-085-06049



Private Road sign near intersection of access road and Road AA1.



Entrance to access road from intersection of Road AA1.

Inspection Photos
Location Name: Wray Mesa 36-34-47-20
API: 05-085-06049



Access road to Wray Mesa 36-34-47-20 location.



Entrance to location. Location drawings include a culvert at the location entrance. A storm water drainage channel was present at the time of this inspection.

Inspection Photos
Location Name: Wray Mesa 36-34-47-20
API: 05-085-06049



View of cut in access road at location entrance.



Location has perimeter fencing. Gate was down at the time of this inspection.

Inspection Photos
Location Name: Wray Mesa 36-34-47-20
API: 05-085-06049



Location photo facing NW from location entrance.



Southeast edge of location.

Inspection Photos
Location Name: Wray Mesa 36-34-47-20
API: 05-085-06049



Typical vegetation within reclaimed area.



Northwest edge of location.

Inspection Photos
Location Name: Wray Mesa 36-34-47-20
API: 05-085-06049



Location photo facing east.



Location overview facing south.

Inspection Photos
Location Name: Wray Mesa 36-34-47-20
API: 05-085-06049



Northeast edge of location.



Location photo facing southwest.

Inspection Photos
Location Name: Wray Mesa 36-34-47-20
API: 05-085-06049



Sediment trap in south corner of location.



Location photo facing northwest.