

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 1 – Spill area with open excavation.



Photo 2 – Fencing around open excavation does not adequately protect access to the site.

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 3 – Open excavation. Impacts appear to remain in situ. Hydrocarbons observed on groundwater.



Photo 4 – Open excavation. Impacts appear to remain in situ. Hydrocarbons observed on groundwater.

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 5 – Soil stored on location. Lining present under soil stockpile but BMPs are inadequate to prevent stormwater runoff.



Photo 6 – Soil stored on location. Lining present under soil stockpile but BMPs are inadequate to prevent stormwater runoff.

Inspection Photos
UPRR 43 PAN AM G Consolidation #2
Remediation Project #16131/Spill ID 478086 (CL)



Photo 7 – Trash on location.



Photo 8 – Trash on location.