

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 1 – Spill area. Trash on location.



Photo 2 – Trash on location.

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 3 – Open excavation. Free product observed on groundwater. Impacts remain in situ.

Photo 4 – Open excavation. Free product observed on groundwater. Impacts remain in situ.

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 5 – Impacted soils remain on surface outside of excavation area.



Photo 6 – Impacted soils remain on surface outside of excavation area. Soils stockpiled on location with inadequate BMPs.

**Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)**



Photo 7 – Soils stored on location with inadequate BMPs

Photo 8 – Soils stored on location with inadequate BMPs

Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)



Photo 9 – Soils stored on location with inadequate BMPs

Photo 10 – Soils stored on location with inadequate BMPs

**Inspection Photos
Paul Heinze #1 Flowline
Spill ID 479232 (AC)**



**Photo 11 – Stained soil from equipment
observed on location.**

Photo 12 – Trash on location