

Inspection Photos
James S Haley Trustee B #2 Flowline
Spill ID 478014 (AC)



Photo 1 – Spill area. Fencing up around open excavation.



Photo 2 – Spill excavation.

Inspection Photos
James S Haley Trustee B #2 Flowline
Spill ID 478014 (AC)



Photo 3 – Spill excavation. Trash observed in open excavation.



Photo 4 – Disturbed area from remediation.

Inspection Photos
James S Haley Trustee B #2 Flowline
Spill ID 478014 (AC)



Photo 5 – Soils stockpiled on location with inadequate BMPs.



Photo 6 – Stained soil observed around open excavation.