

Inspection Photos
Location Name: Carl A Miller A 4
Location ID: 318365



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Carl A Miller A 4
Location ID: 318365



Photo 3 Pump jack



Photo 4 Weeds along access rd

Inspection Photos
Location Name: Carl A Miller A 4
Location ID: 318365



Photo 5 Leaking plug on pump jack gear box



Photo 6 Stained soil in pump jack base