

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/17/2021

Submitted Date:

05/17/2021

Document Number:

699303833

**FIELD INSPECTION FORM**
 Loc ID 318365 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		dnr_cogccenforcement@state.co.us	
,		rwatzman@kpk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241174	WELL	PR	10/06/1976	OW	123-08962	CARL A MILLER A 4	PR

**General Comment:**

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	weeds growing along access road			
Corrective Action	Comply with Rule 603.f			Date: 08/06/2020
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Stained soil in between cement slabs of pump jack base			
Corrective Action:	Comply with rule 1002..(2).D Conduct maintenance on equipment, cleanup stained material and review self inspection processes.			Date: 08/07/2020
Type	OTHER			
Comment:	leaking plug on pump jack gear box			
Corrective Action:	Comply with Rule 605.d			Date: 08/07/2020
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	abricated angle iron			
Corrective Action:				Date:
Type	OTHER			
Comment:	ancillary equipment has fabricated steel pipe and round stock			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Bradenhead	# 1			
Comment:	appears to be plumbed to surface			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			

Comment:	Electric panel, meter box and transformers			
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	electric motor			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 241174 Type: WELL API Number: 123-08962 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 11/02/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 5/17/2021 at approximately 1235 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Carl A. Miller A#4 at API #05-123-08962 in Weld County Colorado. While there, I observed a well site, PR at the time of inspection. follow up to Doc # 699302196.</p> <p>During this inspection the following possible compliance issues were observed and are delinquent:</p> <p>603.f housekeeping: Weeds growing along access road, CA date 8-6-2020 see photo 4.</p> <p>605.d housekeeping: Mechanical issue, Leaking plug on PJ gear box, CA date 8-7-2020 see photo 5.</p> <p>1002..(2).D housekeeping: stained soil between cement slabs of PJ , CA date 8-7-2020 see photo 6.</p> <p>See attached photos.</p> <p>Location is dry, weather is cloudy.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	05/17/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303834	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5431493">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5431493</a>