

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2021

Submitted Date:

05/18/2021

Document Number:

690201547

FIELD INSPECTION FORM

Loc ID 307280 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD State: CO Zip: 8111-

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		efitzgerald@ogrisop.com	
		timothy.thomsen@state.co.us	
ATWATER BONNIE		batwater@ogrisop.com	
Arthur, Denise		denise.arthur@state.co.us	
		rmack@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217354	WELL	PR	01/01/1995	GW	071-06130	APACHE CANYON 14-1	RI

General Comment:

This is a follow up of the previous stormwater management inspection #690201545. The corrective action of the previous inspection has not been performed. Non-compliance with the Rules will be considered for enforcement. See attached photos and additional details within this report.

Operator is directed to perform corrective actions outlined on this inspection report immediately. This inspection is being entered for notification and documentation only and is not intended to provide the Operator the opportunity to resolve the alleged violations without the imposition of a penalty, pursuant to Rule 523.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			
		Gravel	Fail			

Comment: There is vehicle rutting along the main road. There are areas of the road that are not stabilized and stormwater is not properly diverted. Repairing the road only by grading is not sufficient. Areas of erosion along the road needs to be repaired and properly stabilized. This issue has been previously observed and needs to be prevented. BMP's must be implemented in accordance with good engineering practice and must be maintained. Previous corrective action has not been completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/30/2021

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Further stormwater erosion will occur with seasonal high intensity storm events if BMP's are not properly monitored and maintained. BMP's must be installed and maintained for all seasonal storm events to prevent erosion.	CostaR	05/18/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201548	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5432158