

Inspection Photos
Operator: Simcoe
API: 067-09080
Date: 5/17/2021

Acc
rec

Cement p



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with a mixture of grasses such as western wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of the lower, eastern cut-slope facing southward from the northeastern corner.



Photo 4. View of the upper portion of the eastern cut-slope. Revegetation remains sparse here. Black plastic netting debris needs to be removed.



Photo 5. View of bare soils on the upper cut-slope and diversion. Long term soil stabilization measures need to be installed to stabilize soils here.



Photo 6. View of the reference area comprised of ponderosa pine forest with understory of gambel oak, Oregon grape, *Poa secunda*, and serviceberry.