

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2021

Submitted Date:

05/12/2021

Document Number:

690900187

FIELD INSPECTION FORMLoc ID 426365 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

8 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Boyer, David	303-994-0000	david@d90energy.com	
Neidel, Kris		kris.neidel@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections
Spear, Sam	(970) 554-1988	sam@d90energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426354	WELL	PR	10/01/2020	OW	057-06515	Peterson Ridge 1-20H	EI

General Comment:

On May 3, 2021, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of the D90 former SandRidge Exploration & Production LLC's (SandRidge) Peterson Ridge 1-20H Location (Location ID: 426365) API 057-06515. Weather was overcast and temperatures about 35 degrees Fahrenheit. Sandridge signs on location have D90 stickers placed over the name and emergency contact information. Signs have not been updated beyond this. No Form 9 in the database. No evidence of transfer from Sandridge to D90 in database.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s). Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section. Incorrect emergency contact number. CA date taken from Inspection Doc #689805465 (The REU 0681 #1-23H2, Location 449275).		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/11/2021
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. Tank labels should contain: name of operator, operator emergency contact number, tank capacity, tank contents, NFPA label. Inaccurate emergency contact number. CA date taken from Inspection Doc #689805465 (The REU 0681 #1-23H2, Location 449275).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/11/2021
Type	BATTERY		
Comment:	Tank battery sign incomplete. Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section. Inaccurate emergency contact number. CA date taken from Inspection Doc #689805465 (The REU 0681 #1-23H2, Location 449275).		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/11/2021

Emergency Contact Number:

Comment:	Called 405-429-5974 and received message, "we could not complete the call." CA date taken from Inspection Doc #689805465 (The REU 0681 #1-23H2, Location 449275).		
Corrective Action:	Comply with the 605 Series Rules	Date:	05/11/2021

Good Housekeeping:

Type	TRASH		
Comment:	Trash/debris at wellhead and tank battery.		
Corrective Action:	Comply with Rule 606.d .	Date:	05/19/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLS	STEEL AST		,
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. Tank labels should contain: name of operator, operator emergency contact number, tank capacity, tank contents, NFPA label. Inaccurate emergency contact number. CA date taken from Inspection Doc #689805465 (The REU 0681 #1-23H2, Location 449275).				
Corrective Action:	Install sign to comply with Rule 605.h.				Date: 05/11/2021

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. Tank labels should contain: name of operator, operator emergency contact number, tank capacity, tank contents, NFPA label. Inaccurate emergency contact number. CA date taken from Inspection Doc #689805465 (The REU 0681 #1-23H2, Location 449275).				
Corrective Action:	Install sign to comply with Rule 605.h.				Date: 05/11/2021

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Environmental**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: _____

Comment: Oil staining around wellhead.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Date: 06/12/2021

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Signage, emergency contact information inaccurate. Oil staining around the wellhead. Trash/debris	fischera	05/12/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402686795	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5426835
690900188	INSP Photo Peterson Ridge 1-20H Location 426365 20210503	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5426834