

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2021

Submitted Date:

05/12/2021

Document Number:

699303794

FIELD INSPECTION FORM

Loc ID 317839 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		conor.pesicka@state.co.us	
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240044	WELL	SI	11/01/2020	OW	123-07832	MARTIN T. HART B UNIT 1	PR

General Comment:

Empty text area for general comments.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Operator name and emergency number are faded, Sign needs replaced.		
Corrective Action:	Comply with Rule 210.e	Date:	08/20/2020
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Diamond placard is torn and not legible needs replaced.		
Corrective Action:	Comply with Rule 210.d	Date:	08/20/2020

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Ancillary Equipment has fabricated steel pipe		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:	No indication of calibration status		Date:	
Corrective Action:			Date:	
Type:	Ancillary equipment	# 1		
Comment:	Electric Panel, Meter box and Transformers		Date:	
Corrective Action:			Date:	
Type:	Pump Jack	# 1		
Comment:			Date:	
Corrective Action:			Date:	
Type:	Bradenhead	# 1		
Comment:	appears to be plumbed to surface		Date:	
Corrective Action:			Date:	
Type:	Horizontal Heated Separator	# 1		
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	50 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	shares containment with crude tank				
Corrective Action:				Date:	

Wells Served By Facilities Above

AirsID

API Number
123-07832
123-08939

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 240044 Type: WELL API Number: 123-07832 Status: SI Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/12/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 5/12/2021 at approximately 1030 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location. Martin T. Hart B 1 at API #05-123-07832 in Weld County Colorado. While there, I observed a producing wellsite. Follow up to Doc # 699301771. During this inspection the following possible compliance issues were observed and are now delinquent: 210.e general signs: operator name and emergency # are faded and not legible, CA date 8-20-2020 See attached photo 1. 201.d signs/markers tanks/containers: diamond placard is torn and not legible on crude oil tank, CA date 8-20-2020 see attached photo 6. Location is wet and muddy, weather is partly cloudy/clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	05/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402687572	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5427528
699303795	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5427520