

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2021

Submitted Date:

05/12/2021

Document Number:

699303798

FIELD INSPECTION FORMLoc ID 333302 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239920	WELL	PR	01/01/2019	OW	123-07708	VONASEK 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	label not posted on tanks or containers, placard on crude tank is missing		
Corrective Action:	comply with rule 605.h	Date:	08/12/2021
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Information inaccurate on WH sign, old operator #s on sign		
Corrective Action:	Comply with Rule 605.d.	Date:	08/12/2021

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around Horizontal Heated Separator		
Corrective Action:	Comply with Rule 1002..(2).D	Date:	08/12/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	fabricated square tubing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	automation		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:	no card to indicate calibration status, Provide calibration records or calibrate meter. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR).	
Corrective Action:	Comply with Rule 430	Date: 08/12/2021
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	appears to be plumbed to surface	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Shares containment with crude tank				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

AirsID

Wells Served By Facilities Above

API Number

AirsID

API Number

123-07708

123-09218

123-08219

123-09219

123-09229

123-08214

123-08523

123-09233

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 239920 Type: WELL API Number: 123-07708 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/01/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/12/2021 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Vonasek 1 at API #05-123-07708 in Weld County Colorado.</p> <p>While there, I observed a Wellsite & Tank Battery, PR at the time of inspection. During this inspection the following possible compliance issues were observed:</p> <p>605.h signs: crude oil tank placard is missing, CA date 8-12-2021 see photo 5.</p> <p>605.d signs: WH sign has old operator contact #s, CA date 8-12-2021 see photo 1.</p> <p>430 measurement of gas: No card in meter box to indicate calibration status, CA date 8-12-2021.</p> <p>1002..(2).D housekeeping: stained soil around Horiz. Heated Sep. CA date 8-12-2021 see photos 8,9,10,11 and 12.</p> <p>See attached photos.</p> <p>Location: dry, Weather: clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	05/12/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402687574	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5427530
699303799	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5427522