

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/12/2021

Submitted Date:

05/12/2021

Document Number:

700702720

FIELD INSPECTION FORM
 Loc ID 335004 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293631	WELL	PR	05/17/2012	GW	045-15064	FEDERAL SAVAGE 11-11B (RD-11)	PR
293633	WELL	PR	03/26/2012	GW	045-15065	FEDERAL SAVAGE 11-5C (RD-11)	PR
293634	WELL	PR	05/17/2012	GW	045-15067	FEDERAL 10-1D (RD-11)	PR
293636	WELL	PR	05/17/2012	GW	045-15066	FEDERAL 2-13C (RD-11)	PR
293637	WELL	PR	05/17/2012	GW	045-15068	FEDERAL SAVAGE 11-6C (RD-11)	PR
293639	WELL	PR	05/17/2012	GW	045-15069	FEDERAL SAVAGE 11-5 (RD-11)	PR
420604	WELL	PR	05/17/2012	GW	045-20185	FEDERAL SAVAGE 11-3C (RD-11)	PR
420606	WELL	PR	08/01/2020	GW	045-20186	FEDERAL SAVAGE 11-3B (RD-11)	PR
420607	WELL	PR	03/25/2012	GW	045-20187	FEDERAL 11-7C (RD-11)	PR
420608	WELL	PR	05/17/2012	GW	045-20188	FEDERAL SAVAGE 11-3A (RD-11)	PR
424388	WELL	PR	05/17/2012	GW	045-20907	Federal Savage 11-6B (RD-11)	PR

General Comment:

COGCC Inspection Report Summary

On Wednesday 5/12/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus RD 11, at Location # 335004 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following possible compliance issues were observed:

1. No tank battery signage
 2. Lack of stabilization/compaction on location
 3. Debris in tank containment
 4. Staining under tank valve
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	1. No tank battery signage		
Corrective Action:	Comply with rule 605.e	Date:	06/14/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris in tank containment		
Corrective Action:	remove all debris	Date:	06/14/2021
Type	OTHER		
Comment:	Staining under tank valve		
Corrective Action:	remove stained material	Date:	06/14/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 11		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 3	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	chemical tank at well heads in a plastic containment	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 11	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 11	
Comment:	Braden heads have telemetry for monitoring.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	293631	Type:	WELL	API Number:	045-15064	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	293633	Type:	WELL	API Number:	045-15065	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	293634	Type:	WELL	API Number:	045-15067	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	293636	Type:	WELL	API Number:	045-15066	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	293637	Type:	WELL	API Number:	045-15068	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	293639	Type:	WELL	API Number:	045-15069	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420604	Type:	WELL	API Number:	045-20185	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420606	Type:	WELL	API Number:	045-20186	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	420607	Type:	WELL	API Number:	045-20187	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	420608	Type:	WELL	API Number:	045-20188	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	424388	Type:	WELL	API Number:	045-20907	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Compaction	Fail					
Berms						
Retention Ponds						
		Ditches				
Ditches						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.
1. Lack of stabilization/compaction on location

Corrective Action: Install or repair required BMPs

Date: 06/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402687460	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5427428
700702725	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5427423