

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402690459

Date Received:
05/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tyranny Bergin

970-313-5547

EHSCOGCCInspections@pdce.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699103442

Inspection Date: 04/23/2021

FIR Submit Date: 04/23/2021

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 331177

Location Name: NATIONAL HOG FARM-65N63W Number: 17SENE County: _____

Qtrqtr: SENE Sec: 17 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.400750 Longitude: -104.453560

FACILITY - API Number: 05-123-00 Facility ID: 331177

Facility Name: NATIONAL HOG FARM-65N63W Number: 17SENE

Qtrqtr: SENE Sec: 17 Twp: 5N Range: 63W Meridian: 6

Latitude: 40.400750 Longitude: -104.453560

CORRECTIVE ACTIONS:

1 CA# 150016

Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).

Date: 05/21/2021

Response: CA COMPLETED

Date of Completion: 04/29/2021

Operator Comment: The trash has been picked up. The one inch riser has been reconnected to the ECD. The meter has not been calibrated as the meter has been disconnected and is flanged on the flowline. This site will be permanently P&A'd on May 17th, 2021. CA's complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 CA# 150017

Corrective Action: Comply with Rule 606

Date: 05/21/2021

Response: CA COMPLETED

Date of Completion: 04/29/2021

Operator Comment: The trash has been picked up. The one inch riser has been reconnected to the ECD. The meter has not been calibrated as the meter has been disconnected and is flanged on the flowline. This site will be permanently P&A'd on May 17th, 2021. CA's complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 CA# 150018

Corrective Action: Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b

Date: 05/21/2021

Response: CA COMPLETED

Date of Completion: 04/29/2021

Operator Comment: The trash has been picked up. The one inch riser has been reconnected to the ECD. The meter has not been calibrated as the meter has been disconnected and is flanged on the flowline. This site will be permanently P&A'd on May 17th, 2021. CA's complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The trash has been picked up. The one inch riser has been reconnected to the ECD. The meter has not been calibrated as the meter has been disconnected and is flanged on the flowline. This site will be permanently P&A'd on May 17th, 2021. CA's complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyranny Bergin

Signed: _____

Title: EHS Coordinator

Date: 5/16/2021 4:44:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402690459	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files