

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around WH		
Corrective Action:	Comply with Rule 907.e	Date:	12/14/2020
Type	UNUSED EQUIPMENT		
Comment:	unused electric panel leaning on fence		
Corrective Action:	Comply with Rule 603.f	Date:	12/14/2020

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	chain link		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	meter box, electric panel and transformers		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241406 Type: WELL API Number: 123-09195 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/27/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: scout card shows most recent test was on 7-24-2020

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 5/19/2021 at approximately 1415 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Painted Pegasus Petroleum LLC location: Oskarson #3 at API #05-123-09195 in Weld County Colorado. Follow up to Doc # 699302553. While there, I observed a wellsite. SI at the time of inspection all valves are closed and the electric power is off. During this inspection the following possible compliance issues were observed and are now delinquent: 603.f housekeeping: unused electric panel leaning on fence, CA date 12 14 2020. see photo 6. 907.e housekeeping: stained soil around WH, CA date 12-14-2020 see photos 3 & 4. See attached photos. Location is muddy, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	05/19/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303853	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434157