

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/13/2021

Submitted Date:

05/14/2021

Document Number:

689501252

**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 \_\_\_\_\_ Brown, Kari \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Canfield, Chris		chris.canfield@state.co.us	
,		mknop@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463820	SPILL OR RELEASE	CL	07/06/2020		-	Facility #4 North	EI
477605	SPILL OR RELEASE	AC			-	Facility #4 North Consolidation	EI

**General Comment:**

This is a follow-up inspection to Doc # 691201471; Remediation Project No. 13446/Spill ID 463820 (CL) & Spill ID 477605 (AC). No changes have occurred at the site since the previous inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Inspected Facilities							
Facility ID:	463820	Type:	SPILL OR	API Number:	-	Status: CL	Insp. Status: EI
Facility ID:	477605	Type:	SPILL OR	API Number:	-	Status: AC	Insp. Status: EI

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: Field conditions do not indicate that additional work has been done on site. Hydrocarbon impacted soil and groundwater has not been remediated by Operator.

Corrective Action: Per 913.d.(1) Operator is required investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: 01/15/2021

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402689754	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429481">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429481</a>
689501253	Location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429450">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429450</a>