

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2021

Submitted Date:

05/14/2021

Document Number:

689501254

**FIELD INSPECTION FORM**

Loc ID 318201 Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
,		mknop@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478014	SPILL OR RELEASE	AC	09/15/2020		-	James S Haley Trustee B #2 Flowline	EI

**General Comment:**

This is a follow-up inspection to Doc # 691201473; Remediation Project No. 16137/ Spill ID 478014 (AC). Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash on location and in excavation.		
Corrective Action:	Comply with Rule 606. Operator shall provide photo documentation that trash has been removed from excavation prior to backfill.	Date:	05/11/2021
Type	OTHER		
Comment:	Stained soil observed around open excavation that appears to be from equipment leak		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	05/16/2021

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 478014 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Work Plan for Remediation #16137 has been approved, spill should be closed referencing Form 27.

Corrective Action: Request closure for spill ID 478014 via Supplemental Form 19. Date: 10/19/2020

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)
Oily Soil	Piles	Inadequate	
Comment	<span style="color: blue;">Approximately 10 cubic yards of impacted soils remain on location with inadequate BMPs.</span>		
Corrective Action	<span style="color: red;">Repair/improve BMPs or remove oily waste from location. Comply with Rule 913.b. (5)b.iv</span>		Date: <u>10/10/2020</u>

**Spill/Remediation:**

Comment: Spill excavation is open (approx. size 25'x12'x10'). No groundwater was observed in the open excavation. Per Form 27 Submitted 04/09/2021 (Document #402653871) remediation was scheduled between 9/4/2020 and 1/18/2021.

Corrective Action: Per Rule 913.d.(2) Operator shall submit a Supplemental Form 27 with an updated Implementation Schedule at least 14 days in advance of any schedule changes. Operator will provide notice to COGCC EPS Nikki Graber (nikki.graber@state.co.us) at least 48 hours prior to backfill or any sampling events preformed on location. Note that samples collected must be analyzed for Table 915-1 parameters. Date: 04/19/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402689755	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429482">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429482</a>
689501255	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429451">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5429451</a>